

Sandon and Burston PC – Highways Log

All issues reported via the SCC Report IT app.

Issue details	SCC Highways Reference number	Date reported	SCC updates
blocked gullies on A51 by the Dog and Doublet pub - ST18 0JD	4421164	07.01.2025	13.01.2025 SCC update - A highways officer has assessed the site and has deemed it not requiring safety intervention at this time, however a work instruction has been raised for forward planning. The report will remain on our records and the location will be routinely inspected for any changes in the level of risk.
Missing Reflective Strips on both ends and both sides of the Single Lane Bridge (Canal), Sandon Bank, B5066 - nearest postcode ST18 0DJ	4442860	05.06.2025	16.06.2025 We have visited the location provided with your report but have been unable to identify any defects that require remedial works at this time. SCC Closed it on system. Reported again 16.06.2025 and sent to SCC Ward Councillor. 28.06.2025 - SCC updated: We have visited the location provided with your report but have been unable to identify any defects that require remedial works at this time. 22.07.2025 reported again with photos, requesting signage on walls of bridge, upgrading the reflectors in the verge and signage at both ends advising of pedestrians in road or Give way to pedestrians signs. 12.08.2025 SCC updated The issue that you have raised will be
	4444118	16.06.2025	
		28.06.2025	
	4448048	22.07.2025	
		12.08.2025	

			discussed by community representatives, led by your locally elected County Councillor Andrew Mynors. This review of highway and transportation issues in your area will be conducted on a bi-annual basis in order to establish an agreed work programme which will be widely publicised within the local community.
Overgrown verges Burston	4395242	24.06.2025 CLOSED	Reported, then told only do these once a year SCC update: We have not yet been able to coordinate resources to resolve the enquiry you raised, due to high demand for reactive maintenance work across our road network.
Bollard knocked over on A51/Milwich Road – ST18 0DN	4447285	15.07.2025 29.07.2025	Reported and included a photo of the bollard. SCC message: The information you provided has been reviewed and currently, the defect does not warrant diverting resources on an emergency basis. SCC updated: A highways officer has assessed the site you reported and arranged a non-urgent work instruction. The outcome of the assessment means this defect does not pose an immediate risk to public safety.